


AIRPORT DIAGRAM

AL-330 (FAA)

PORTLAND INTL (PDX)

PORTLAND, OREGON

NW-1, 30 AUG 2007 to 27 SEP 2007



CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

AIRPORT DIAGRAM

PORTLAND, OREGON

PORTLAND INTL (PDX)